

FIG. 19 AXIAL PHOTOGRAPH POLAROID CASSETTE BRACKET FITTED TO CAD4 GONIOMETER.

- 1 CASSETTE ADJUSTMENT (FACTORY SETTING).
- 2 PIVOT.
- 3 SHOCK ABSORBER.
- 4 CASSETTE ARM.
- 5 THREADED FIXATION HOLES AND BLIND LOCATION HOLES IN POLAROID XR7-57/3 CASSETTE.
- 6 POLAROID NON-METRIC SCREWS.
- 7 LOCATING PIN.
- 8 SCREW.
- 9 POLAROID CASSETTE LOCATION FOR AXIAL PHOTOGRAPHS.




FIG. 20 STANDARD POLAROID CASSETTE BRACKET FITTED TO CAD4 GONIOMETER. FOR DETAILS SEE FIG. 12